

F-4000 FRAME SIZE				
Model Number	Rockwell P/N	Elwood P/N	List Price	Rebuild Price
F-4030-Q-H00AA	193488	999-001-0390	\$3,596	\$2,158
FSM430	401-34318-01	999-001-0390	\$3,596	\$2,158
F-4030-Q-H00AN	193489	999-001-0392	\$3,596	\$2,158
FSM430 56C	401-34393-00	999-001-0392	\$3,596	\$2,158
F-4030-Q-H04AA	193490	999-001-0391	\$4,415	\$2,649
FSM430 B24	401-34318-20	999-001-0391	\$4,416	\$2,650
F-4030-Q-H04AN	193491	999-001-0393	\$4,416	\$2,650
FSM430 56C B24	401-34318-26	999-001-0393	\$4,416	\$2,650
F-4030-Q-K00AA	195853	999-001-0409	\$3,844	\$2,306
F-4030-Q-K00AN	195858	999-001-0413	\$3,844	\$2,306
F-4030-Q-K04AA	195857	999-001-0412	\$4,663	\$2,798
F-4030-Q-K04AN	195859	999-001-0414	\$4,663	\$2,798
F-4050-Q-H00AA	193493	999-001-0394	\$4,254	\$2,552
FSM460	401-34320-01	999-001-0394	\$4,254	\$2,552
F-4050-Q-H00AN	193494	999-001-0395	\$4,254	\$2,552
FSM460 56C	401-34320-06	999-001-0395	\$4,254	\$2,552
F-4050-Q-H01AN	195880	999-001-0426	\$6,187	\$3,712
F-4050-Q-H04AA	193495	999-001-0396	\$5,727	\$3,436
FSM460 B24	401-34320-20	999-001-0396	\$5,727	\$3,436
F-4050-Q-H04AN	193496	999-001-0397	\$5,727	\$3,436
F-4050-Q-K00AA	195860	999-001-0415	\$4,336	\$2,602
FSM460 E5000	401-34320-50	999-001-0415	\$4,336	\$2,602
F-4050-Q-K00AN	195862	999-001-0417	\$4,336	\$2,602
F-4050-Q-K04AA	195861	999-001-0416	\$5,808	\$3,485
F-4050-Q-K04AN	195863	999-001-0418	\$5,808	\$3,485
F-4075-R-H00AA	193497	999-001-0398	\$4,827	\$2,896
FSM490	401-34322-01	999-001-0398	\$4,827	\$2,896
F-4075-R-H00AN	193498	999-001-0399	\$4,827	\$2,896
F-4075-R-H01AA	401-34323-01	999-001-0427	\$6,922	\$4,153
F-4075-R-H04AA	193499	999-001-0400	\$6,301	\$3,781
FSM490 B24	401-34322-20	999-001-0400	\$6,301	\$3,781
F-4075-R-H01AN		999-001-0389	\$6,922	\$2,267
F-4075-R-H04AN	193500	999-001-0401	\$6,301	\$3,781
F-4075-R-K00AA	195852	999-001-0408	\$5,073	\$3,044
F-4075-R-K00AN	193856	999-001-0411	\$5,073	\$3,044
F-4075-R-K04AA	195864	999-001-0419	\$6,464	\$3,879
F-4075-R-K04AN	195865	999-001-0420	\$6,464	\$3,879

*Availability is updated weekly and subject to change. Call to confirm.

**Consult factory for model numbers not listed.

***All motors built with original design, documentation, and equipment

<https://www.elwood.com/motors/fseries/F-Series.html>

F-6000 FRAME SIZE				
Model Number	Rockwell P/N	Elwood P/N	List Price	Rebuild Price
F-6100-R-H00AA	193501	999-001-0402	\$5,403	\$3,242
FSM610	401-34324-01	999-001-0402	\$5,403	\$3,242
F-6100-R-H04AA	193502	999-001-0403	\$7,149	\$4,289
F-6100-R-K00AA	193855	999-001-0410	\$5,735	\$3,441
F-6100-R-K04AA	195866	999-001-0421	\$7,308	\$4,385
F-6200-R-H00AA	193503	999-001-0404	\$7,089	\$4,253
FSM620	401-34326-01	999-001-0404	\$7,089	\$4,253
F-6200-R-H04AA	193504	999-001-0405	\$8,578	\$5,147
F-6200-R-K00AA	195867	999-001-0422	\$7,420	\$4,452
F-6200-R-K04AA	195868	999-001-0423	\$8,793	\$5,276
F-6300-R-H00AA	193505	999-001-0406	\$9,254	\$5,552
FSM630	401-34328-01	999-001-0406	\$9,254	\$5,552
F-6300-R-H04AA	193506	999-001-0407	\$10,744	\$6,446
F-6300-R-K00AA	195869	999-001-0424	\$9,586	\$5,752
F-6300-R-K04AA	195870	999-001-0425	\$10,909	\$6,545

*Availability is updated weekly and subject to change. Call to confirm.

**Consult factory for model numbers not listed.

***All motors built with original design, documentation, and equipment