

2018 PRICE LIST: 1326AB-SERIES REPLACEMENT MOTORS				
1326AB-B4xxx FRAME SIZE				
Catalog (Model) Number	Rockwell P/N	Elwood P/N	List Price	New Motor Availability*
1326AB-B410G-21	199156.00	999-001-0677	\$2,397.00	Stock
1326AB-B410G-21-K4	199166.00	999-001-0678	\$4,046.00	4-6 Weeks
1326AB-B410G-21-K4L	199204.00	999-001-0679	\$4,705.00	4 Weeks
1326AB-B410G-21-L	199205.00	999-001-0680	\$2,817.00	4-6 Weeks
1326AB-B410G-M2K4L	199256.00	999-001-0681	\$6,193.00	4-6 Weeks
1326AB-B410G-M2L	199255.00	999-001-0682	\$4,066.00	4-6 Weeks
1326AB-B410G-M2LS	199255.60	999-001-0683	\$4,066.00	4-6 Weeks
1326AB-B410G-S2K4L	199254.00	999-001-0684	\$5,526.00	4-6 Weeks
1326AB-B410G-S2K4LS	199254.60	999-001-0685	\$5,526.00	4-6 Weeks
1326AB-B410G-S2L	199253.00	999-001-0686	\$3,401.00	4-6 Weeks
1326AB-B410G-S2LS	199253.60	999-001-0687	\$3,401.00	4-6 Weeks
1326AB-B410J-21	199181.00	999-001-0688	\$2,758.00	4-6 Weeks
1326AB-B410J-21-K4	199184.00	999-001-0689	\$4,046.00	4-6 Weeks
1326AB-B410J-21-L	199207.00	999-001-0690	\$2,689.00	4-6 Weeks
1326AB-B410J-M2K4L	199260.00	999-001-0691	\$5,812.00	4-6 Weeks
1326AB-B410J-M2L	199259.00	999-001-0692	\$4,066.00	4-6 Weeks
1326AB-B410J-S2L	199257.00	999-001-0693	\$3,401.00	4-6 Weeks
1326AB-B420E-21	199153.00	999-001-0694	\$2,934.00	Stock
1326AB-B420E-21-K4	199163.00	999-001-0695	\$4,096.00	4-6 Weeks
1326AB-B420E-21-K4L	199208.00	999-001-0696	\$4,396.00	4-6 Weeks
1326AB-B420E-21-L	199209.00	999-001-0697	\$3,167.00	4-6 Weeks
1326AB-B420E-21-X92	199231.00	999-001-0698		Obsolete
1326AB-B420E-21-X51	199227.00	999-001-0972	\$3,546.00	4-6 Weeks
1326AB-B420E-M2K4L	199264.00	999-001-0699	\$5,866.00	4-6 Weeks
1326AB-B420E-M2K4LS	199264.60	999-001-0700	\$5,866.00	4 Weeks
1326AB-B420E-M2L	199263.00	999-001-0701	\$4,571.00	4-6 Weeks
1326AB-B420E-M2LS	199263.60	999-001-0702	\$4,571.00	4-6 Weeks
1326AB-B420E-S2K4L	199262.00	999-001-0703	\$5,201.00	4-6 Weeks
1326AB-B420E-S2K4LS	199262.60	999-001-0704	\$5,201.00	4-6 Weeks
1326AB-B420E-S2L	199261.00	999-001-0705	\$3,904.00	4-6 Weeks
1326AB-B420E-S2LS	199261.60	999-001-0706	\$3,904.00	4-6 Weeks
1326AB-B420H-21	199182.00	999-001-0707	\$3,061.00	Stock
1326AB-B420H-21-K4	199185.00	999-001-0708	\$4,285.00	4-6 Weeks
1326AB-B420H-21-K4L	199210.00	999-001-0709	\$4,584.00	4-6 Weeks
1326AB-B420H-21-L	199211.00	999-001-0710	\$3,111.00	4-6 Weeks
1326AB-B420H-M2K4L	199268.00	999-001-0711	\$6,066.00	4-6 Weeks
1326AB-B420H-M2K4LS	199268.60	999-001-0712	\$6,066.00	4-6 Weeks
1326AB-B420H-M2L	199267.00	999-001-0713	\$4,363.00	4-6 Weeks
1326AB-B420H-M2LS	199267.60	999-001-0714	\$4,363.00	4-6 Weeks
1326AB-B420H-S2K4L	199266.00	999-001-0715	\$5,400.00	4-6 Weeks
1326AB-B420H-S2K4LS	199266.60	999-001-0716	\$5,400.00	4-6 Weeks
1326AB-B420H-S2L	199265.00	999-001-0717	\$3,697.00	4-6 Weeks
1326AB-B430E-21	199155.00	999-001-0718	\$3,494.00	Stock
1326AB-B430E-21-K4	199165.00	999-001-0719	\$4,428.00	4-6 Weeks
1326AB-B430E-21-K4L	199212.00	999-001-0720	\$4,933.00	4-6 Weeks
1326AB-B430E-21-L	199213.00	999-001-0721	\$3,381.00	4-6 Weeks
1326AB-B430E-21-X93	Obsolete	999-001-0644		Obsolete
1326AB-B430E-M2K4L	199272.00	999-001-0722	\$6,434.00	4-6 Weeks
1326AB-B430E-M2K4LS	199272.60	999-001-0723	\$6,434.00	4-6 Weeks
1326AB-B430E-M2L	199271.00	999-001-0724	\$4,634.00	4-6 Weeks
1326AB-B430E-M2LS	199271.60	999-001-0725	\$4,634.00	4-6 Weeks
1326AB-B430E-S2K4L	199270.00	999-001-0726	\$5,768.00	4-6 Weeks
1326AB-B430E-S2K4LS	199270.60	999-001-0727	\$5,768.00	4-6 Weeks
1326AB-B430E-S2L	199269.00	999-001-0728	\$3,968.00	4-6 Weeks
1326AB-B430E-S2LS	199269.60	999-001-0729	\$3,968.00	4-6 Weeks
1326AB-B430G-21	199183.00	999-001-0730	\$3,494.00	4-6 Weeks
1326AB-B430G-21-K4	199186.00	999-001-0731	\$4,633.00	4-6 Weeks
1326AB-B430G-M2K4L	199276.00	999-001-0732	\$6,487.00	4-6 Weeks
1326AB-B430G-M2L	199275.00	999-001-0733	\$4,629.00	4-6 Weeks
1326AB-B430G-N2LS	199275.60	999-001-1074	\$4,629.00	4-6 Weeks
1326AB-B430G-S2K4L	199274.00	999-001-0734	\$5,822.00	4-6 Weeks
1326AB-B430G-S2K4LS	199274.60	999-001-0735	\$5,822.00	Stock
1326AB-B430G-S2L	199273.00	999-001-0736	\$3,968.00	4-6 Weeks
1326AB-B430G-S2LS	199273.60	999-001-0737	\$3,968.00	4-6 Weeks

*Availability is updated weekly and subject to change. Call to confirm.

**Consult factory for model numbers not listed.

***All motors built with original design, documentation, and equipment

2018 PRICE LIST: 1326AB-SERIES REPLACEMENT MOTORS				
1326AB-B5xxx FRAME SIZE				
Catalog (Model) Number	Rockwell P/N	Elwood P/N	List Price	New Motor Availability*
1326AB-B515E-21	199459.00	999-001-0738	\$3,527.00	Stock
1326AB-B515E-21-K5	199473.00	999-001-0739	\$5,097.00	4-6 Weeks
1326AB-B515E-21-K5L	199512.00	999-001-0740	\$5,399.00	4-6 Weeks
1326AB-B515E-21-L	199513.00	999-001-0741	\$3,517.00	4-6 Weeks
1326AB-B515E-21-X51	199531.00	999-001-0742	\$4,362.00	4-6 Weeks
1326AB-B515E-M2K5L	199565.00	999-001-0743	\$6,925.00	4-6 Weeks
1326AB-B515E-M2K5LS	199565.60	999-001-0744	\$6,925.00	4-6 Weeks
1326AB-B515E-M2L	199564.00	999-001-0745	\$5,632.00	4-6 Weeks
1326AB-B515E-M2LS	199564.60	999-001-0746	\$5,632.00	4-6 Weeks
1326AB-B515E-S2K5L	199563.00	999-001-0747	\$6,259.00	4-6 Weeks
1326AB-B515E-S2K5LS	199563.60	999-001-1075	\$6,259.00	4-6 Weeks
1326AB-B515E-S2L	199562.00	999-001-0748	\$4,274.00	4-6 Weeks
1326AB-B515E-S2LS	199562.60	999-001-0749	\$4,274.00	4-6 Weeks
1326AB-B515G-21	199493.00	999-001-0750	\$3,220.00	4-6 Weeks
1326AB-B515G-21-K5	199495.00	999-001-0751	\$5,097.00	4-6 Weeks
1326AB-B515G-21-K5L	199514.00	999-001-0752	\$5,392.00	4-6 Weeks
1326AB-B515G-21-L	199515.00	999-001-0753	\$3,517.00	4-6 Weeks
1326AB-B515G-M2K5L	199569.00	999-001-0754	\$6,917.00	4-6 Weeks
1326AB-B515G-M2K5LS	199569.60	999-001-0755	\$6,917.00	4-6 Weeks
1326AB-B515G-M2L	199568.00	999-001-0756	\$4,940.00	4-6 Weeks
1326AB-B515G-M2LS	199568.60	999-001-0757	\$4,940.00	4-6 Weeks
1326AB-B515G-S2K5L	199567.00	999-001-0758	\$6,251.00	4-6 Weeks
1326AB-B515G-S2K5LS	199567.60	999-001-0759	\$6,251.00	4-6 Weeks
1326AB-B515G-S2L	199566.00	999-001-0760	\$4,274.00	Stock
1326AB-B515G-S2LS	199566.60	999-001-0761	\$4,274.00	4-6 Weeks
1326AB-B520E-21	199460.00	999-001-0762	\$3,988.00	Stock
1326AB-B520E-21-K5	199474.00	999-001-0763	\$5,418.00	4-6 Weeks
1326AB-B520E-21-L	199517.00	999-001-0764	\$3,786.00	4-6 Weeks
1326AB-B520E-M2K5L	199573.00	999-001-0765	\$7,260.00	4-6 Weeks
1326AB-B520E-M2K5LS	199573.60	999-001-0766	\$7,260.00	4-6 Weeks
1326AB-B520E-M2L	199572.00	999-001-0767	\$5,224.00	Stock
1326AB-B520E-M2LS	199572.60	999-001-0768	\$5,224.00	4-6 Weeks
1326AB-B520E-S2K5L	199571.00	999-001-0769	\$6,595.00	Stock
1326AB-B520E-S2L	199570.00	999-001-0770	\$4,558.00	4-6 Weeks
1326AB-B520E-S2LS	199570.60	999-001-0771	\$4,558.00	4-6 Weeks
1326AB-B520F-21	199494.00	999-001-0772	\$3,821.00	4-6 Weeks
1326AB-B520F-21-K5	199496.00	999-001-0773	\$5,415.00	Stock
1326AB-B520F-21-K5L	199518.00	999-001-0774	\$5,727.00	4-6 Weeks
1326AB-B520F-21-L	199519.00	999-001-0775	\$3,786.00	4-6 Weeks
1326AB-B520F-M2K5L	199577.00	999-001-0776	\$7,272.00	4-6 Weeks
1326AB-B520F-M2K5LS	199577.60	999-001-0777	\$7,272.00	Stock
1326AB-B520F-M2L	199576.00	999-001-0778	\$5,915.00	4-6 Weeks
1326AB-B520F-M2LS	199576.60	999-001-0779	\$5,915.00	4-6 Weeks
1326AB-B520F-S2K5L	199575.00	999-001-0780	\$6,606.00	4-6 Weeks
1326AB-B520F-S2K5LS	199575.60	999-001-0781	\$6,606.00	4-6 Weeks
1326AB-B520F-S2L	199574.00	999-001-0782	\$5,361.00	4-6 Weeks
1326AB-B520F-S2LS	199574.60	999-001-0783	\$5,361.00	6-8 Weeks
1326AB-B530E-21	199462.00	999-001-0784	\$4,765.00	4-6 Weeks
1326AB-B530E-21-K5	199476.00	999-001-0785	\$6,167.00	4-6 Weeks
1326AB-B530E-21-K5L	199520.00	999-001-0786	\$6,755.00	4-6 Weeks
1326AB-B530E-21-L	199521.00	999-001-0787	\$5,063.00	Stock
1326AB-B530E-21-X93	199555.00	999-001-0788	\$8,683.00	4-6 Weeks
1326AB-B530E-21-Z06	199535.00	999-001-0977	\$6,326.00	4-6 Weeks
1326AB-B530E-M2K5L	199581.00	999-001-0789	\$8,356.00	4-6 Weeks
1326AB-B530E-M2K5LS	199581.60	999-001-0790	\$8,356.00	4-6 Weeks
1326AB-B530E-M2L	199580.00	999-001-0791	\$7,470.00	4-6 Weeks
1326AB-B530E-M2LS	199580.60	999-001-0792	\$7,470.00	Stock
1326AB-B530E-S2K5L	199579.00	999-001-0793	\$7,690.00	4-6 Weeks
1326AB-B530E-S2K5LS	199579.60	999-001-0794	\$7,690.00	4-6 Weeks
1326AB-B530E-S2L	199578.00	999-001-0795	\$5,904.00	4-6 Weeks
1326AB-B530E-S2LS	199578.60	999-001-0796	\$5,904.00	4-6 Weeks

*Availability is updated weekly and subject to change. Call to confirm.

**Consult factory for model numbers not listed.

***All motors built with original design, documentation, and equipment

2018 PRICE LIST: 1326AB-SERIES REPLACEMENT MOTORS				
1326AB-B7xxx FRAME SIZE				
Catalog (Model) Number	Rockwell P/N	Elwood P/N	List Price	New Motor Availability*
1326AB-B720E-21	199760.00	999-001-0797	\$5,905.00	Stock
1326AB-B720E-21-K7	199774.00	999-001-0798	\$7,493.00	4-6 Weeks
1326AB-B720E-21-K7L	199794.00	999-001-0799	\$7,157.00	4-6 Weeks
1326AB-B720E-21-L	199795.00	999-001-0800	\$6,210.00	4-6 Weeks
1326AB-B720E-M2K7L	199844.00	999-001-0801	\$8,779.00	4-6 Weeks
1326AB-B720E-M2K7LS	199844.60	999-001-0802	\$8,779.00	4-6 Weeks
1326AB-B720E-M2L	199843.00	999-001-0803	\$7,781.00	Stock
1326AB-B720E-M2LS	199843.60	999-001-0804	\$7,781.00	4-6 Weeks
1326AB-B720E-S2K7L	199842.00	999-001-0805	\$8,114.00	4-6 Weeks
1326AB-B720E-S2L	199841.00	999-001-0806	\$6,804.00	Stock
1326AB-B720E-S2LS	199841.60	999-001-0807	\$6,804.00	Stock
1326AB-B720F-21	199805.00	999-001-0808	\$6,422.00	4-6 Weeks
1326AB-B720F-21-K7	199831.00	999-001-1003	\$7,493.00	4-6 Weeks
1326AB-B720F-M2K7L	199861.00	999-001-0809	\$9,701.00	4-6 Weeks
1326AB-B720F-M2K7LS	199861.60	999-001-0810	\$9,701.00	4-6 Weeks
1326AB-B720F-M2L	199856.00	999-001-0811	\$8,028.00	4-6 Weeks
1326AB-B720F-M2LS	199856.60	999-001-0812	\$8,028.00	4-6 Weeks
1326AB-B720F-S2K7L	199860.00	999-001-0813	\$9,035.00	4-6 Weeks
1326AB-B720F-S2L	199859.00	999-001-0814	\$7,362.00	4-6 Weeks
1326AB-B720F-S2LS	199859.60	999-001-0815	\$7,362.00	Stock
1326AB-B730E-21	199762.00	999-001-0816	\$7,614.00	4-6 Weeks
1326AB-B730E-21-K7	199776.00	999-001-0817	\$8,905.00	4-6 Weeks
1326AB-B730E-M2K7L	199848.00	999-001-0818	\$11,154.00	4-6 Weeks
1326AB-B730E-M2K7LS	199848.60	999-001-0819	\$11,154.00	4-6 Weeks
1326AB-B730E-M2L	199847.00	999-001-0820	\$9,262.00	6-8 Weeks
1326AB-B730E-M2LS	199847.60	999-001-0821	\$9,262.00	6-8 Weeks
1326AB-B730E-S2K7L	199846.00	999-001-0822	\$10,281.00	4-6 Weeks
1326AB-B730E-S2L	199845.00	999-001-0823	\$8,595.00	6-8 Weeks
1326AB-B730E-S2LS	199845.60	999-001-0824	\$8,595.00	6-8 Weeks
1326AB-B730E-X113	199858.00	999-001-0999	\$10,481.00	6-8 Weeks
1326AB-B740C-21	199757.00	999-001-0825	\$7,979.00	4-6 Weeks
1326AB-B740C-21-K7	199771.00	999-001-0826	\$9,578.00	4-6 Weeks
1326AB-B740C-M2K7L	199852.00	999-001-0827	\$11,657.00	4-6 Weeks
1326AB-B740C-M2L	199851.00	999-001-0828	\$10,830.00	4-6 Weeks
1326AB-B740C-M2LS	199851.60	999-001-0829	\$10,830.00	4-6 Weeks
1326AB-B740C-S2L	199849.00	999-001-0830	\$10,165.00	4-6 Weeks
1326AB-B740C-S2LS	199849.60	999-001-0831	\$10,165.00	4-6 Weeks
1326AB-B740E-21	199764.00	999-001-0832	\$8,796.00	4-6 Weeks
1326AB-B740E-21-K7	199778.00	999-001-0833	\$10,403.00	4-6 Weeks
1326AB-B740E-21-L	199834.00	999-001-0975	\$9,114.00	4-6 Weeks
1326AB-B740E-M2K7L	199864.00	999-001-0834	\$12,229.00	4-6 Weeks
1326AB-B740E-M2K7LS	199864.60	999-001-0835	\$12,229.00	4-6 Weeks
1326AB-B740E-M2L	199854.00	999-001-0836	\$10,534.00	4-6 Weeks
1326AB-B740E-M2LS	199854.60	999-001-0837	\$10,534.00	Stock
1326AB-B740E-S2K7L	199863.00	999-001-0838	\$11,562.00	4-6 Weeks
1326AB-B740E-S2L	199862.00	999-001-0839	\$9,867.00	4-6 Weeks
1326AB-B740E-S2LS	199862.60	999-001-0840	\$9,867.00	4-6 Weeks

*Availability is updated weekly and subject to change. Call to confirm.

**Consult factory for model numbers not listed.

***All motors built with original design, documentation, and equipment