

PRICE LIST: H-SERIES REPLACEMENT MOTORS						
2-INCH FRAME						
Model Number	Rockwell P/N	Elwood P/N	List Price	Rare Earth Surcharge	New Motor Availability*	Rebuild Price
H-2005 (HSM205)	401-34431-00		n/a	n/a	Refurbish/Rebuild	\$805
H-2005-K-F00AA	195871		n/a	n/a	Refurbish/Rebuild	\$805
H-2005-K-H00AA	193457		n/a	n/a	Refurbish/Rebuild	\$805
3-INCH FRAME						
Model Number	Rockwell P/N	Elwood P/N	List Price	Rare Earth Surcharge	New Motor Availability*	Rebuild Price
1326AS-B310H-21	163569	999-001-0011	\$1,418	\$11.58	Stock	\$851
1326AS-B310H-21-K3		999-001-0111	\$2,068	\$11.58	4 Weeks	\$1,241
1326AS-B330H-21	163570	999-001-0012	\$1,478	\$34.74	2-3 Weeks	\$887
1326AS-B330H-21-A	195733	999-001-0027	\$2,373	\$34.74	4 Weeks	\$1,424
1326AS-B330H-21-K3		999-001-0065	\$2,121	\$34.74	4 Weeks	\$1,273
H-3007	163569	Call for P/N	\$1,297	\$11.58	4 Weeks	\$778
H-3007 (HSM307)	401-34432-00	999-001-0048	\$1,297	\$11.58	Stock	\$778
H-3007-N-H00AA	193458	999-001-0048	\$1,297	\$11.58	Stock	\$778
H-3007-N-H00AA-AA		999-001-0077	\$1,341	\$11.58	Stock	\$805
H-3007-N-H01AA		999-001-0049	\$1,686	\$11.58	4 Weeks	\$1,012
H-3007-N-H01AA-AA		999-001-0155	\$1,729	\$11.58	4 Weeks	\$1,007
H-3007-N-H04AA	193459	999-001-0003	\$1,556	\$11.58	Stock	\$934
H-3007/24V BRK	163623	Call for P/N	\$1,556	\$11.58	4-6 Weeks	\$934
H-3016		999-000-9982	\$1,310	\$34.74	Stock	\$786
H-3016 (HSM320)	401-34433-00	999-000-9982	\$1,310	\$34.74	Stock	\$786
H-3016-N-H00AA	193460	999-000-9982	\$1,310	\$34.74	Stock	\$786
H-3016-N-H00AA-AA		999-001-0154	\$1,390	\$34.74	4 Weeks	\$810
H-3016-N-H00AX	6133-01-008	999-001-0099	\$1,418	\$34.74	4 Weeks	\$851
H-3016-N-H01AA	195850	999-001-0054	\$1,778	\$34.74	4 Weeks	\$1,067
H-3016-N-H01AA-AA		999-001-0156	\$1,850	\$34.74	Stock	\$1,078
H-3016-N-H04AA	193461	999-000-9997	\$1,778	\$34.74	Stock	\$1,067
H-3016-N-K00AA	195814	Call for P/N	\$1,369	\$34.74	4-6 Weeks	\$821
H-3016-N-K04AA	6133-01-510	999-000-9986	\$1,975	\$34.74	4 Weeks	\$1,185
H-3016/24V BRK	163624	Call for P/N	\$1,778	\$34.74	4-6 Weeks	\$1,067
H-3016/24V BRK (HSM320B24)	401-34433-20	999-000-9997	\$1,778	\$34.74	Stock	\$1,067
H-3016/90V BRK (HSM320B90)	401-34433-90	Call for P/N	\$1,778	\$34.74	4-6 Weeks	\$1,067
H-3016/Flying Leads	191893	Call for P/N	\$1,469	\$34.74	4-6 Weeks	\$881
H-3040	164268	Call for P/N	\$1,371	\$65.00	Call for Availability	\$823
W-3016-N-H00AA	6333-02-802	999-001-0186	\$2,382	\$34.74	4-6 Weeks	\$1,429
W-3016-N-H00AB	6333-02-002	Call for P/N	\$2,500	\$34.74	4-6 Weeks	\$1,500

*Availability is updated weekly and subject to change. Call to confirm.

**Consult factory for model numbers not listed.

***All motors built with original design, documentation, and equipment

Contact Elwood:

Linda Richmond phone: 262-637-6591 x413 email: linda.richmond@elwood.com

Lisa Woodward phone: 262-637-6591 x474 email: lisa.woodward@elwood.com

John Hoepfner phone: 262-637-6591 x495 email: john.hoepfner@elwood.com

PRICE LIST: H-SERIES REPLACEMENT MOTORS						
4-INCH FRAME						
Model Number	Rockwell P/N	Elwood P/N	List Price	Rare Earth Surchage	New Motor Availability*	Rebuild Price
1326AS-B420G-21	195734	999-001-0005	\$2,461	\$38.95	Stock	\$1,477
1326AS-B420G-21-AA		999-001-0060	\$2,964	\$38.95	Stock	\$1,644
1326AS-B420G-21-A		999-001-0028	\$2,677	\$38.95	4-6 Weeks	\$1,606
1326AS-B420G-21-K4		999-001-0084	\$2,807	\$38.95	4 Weeks	\$1,684
1326AS-B440G-21	163572	999-000-9990	\$2,515	\$77.89	2-3 Weeks	\$1,509
1326AS-B440G-21-A	195735	999-001-0029	\$2,807	\$77.89	4-6 Weeks	\$1,684
1326AS-B440G-21-K4		999-001-0148	\$2,861	\$77.89	Stock	\$1,717
1326AS-B460F-21		999-001-0007	\$2,569	\$116.84	Stock	\$1,541
1326AS-B460F-21-K4	163627	999-000-9987	\$2,915	\$116.84	Stock	\$1,749
H-4030	163571	Call for P/N	\$1,461	\$35.95	4 Weeks	\$877
H-4030 (HSM430)	401-34434-00	999-000-9980	\$1,461	\$35.95	Stock	\$877
H-4030-M-H00AA	193462	999-001-0070	\$1,445	\$35.95	4 Weeks	\$867
H-4030-M-H00AN	193463	Call for P/N	\$1,482	\$35.95	4-6 Weeks	\$889
H-4030-M-H00AX	6142-01-002	999-001-0107	\$1,488	\$35.95	Stock	\$893
H-4030-M-H04AA	193464	999-001-0096	\$2,050	\$35.95	4 Weeks	\$1,230
H-4030-M-H04AX		999-001-0125	\$2,158	\$35.95	4 Weeks	\$1,295
H-4030-P-H00AA	193465	999-000-9980	\$1,461	\$35.95	Stock	\$877
H-4030-P-H00AA-AA		999-001-0130	\$1,498	\$35.95	4 Weeks	\$831
H-4030-P-H00AN	193466	Call for P/N	\$1,482	\$35.95	4-6 Weeks	\$889
H-4030-P-H00AX		999-001-0010	\$1,488	\$35.95	4 Weeks	\$825
H-4030-P-H00KD	193467	999-001-0023	\$1,569	\$35.95	4 Weeks	\$941
H-4030-P-H01AA		Call for P/N	\$2,115	\$35.95	4-6 Weeks	\$1,269
H-4030-P-H04AA	193468	999-001-0098	\$2,050	\$35.95	4 Weeks	\$1,230
H-4030-P-H04AN	6142-02-857	Call for P/N	\$2,066	\$35.95	4-6 Weeks	\$1,240
H4030-P-H04AX		999-001-0147	\$2,158	\$35.95	4 Weeks	\$1,197
H-4030-P-J00AB	6142-01-032	999-001-0198	\$1,909	\$35.95	4-6 Weeks	\$1,145
H-4030-P-J04AB	6142-01-028	Call for P/N	\$2,883	\$35.95	4-6 Weeks	\$1,730
H-4030/24V	401-34434-20	Call for P/N	\$2,050	\$35.95	4-6 Weeks	\$1,230
H-4030/24V (HSM430B24)		Call for P/N	\$2,050	\$35.95	4-6 Weeks	\$1,230
H-4030/24V-AB	163625	Call for P/N	\$2,050	\$35.95	4-6 Weeks	\$1,230
H-4050	163572	Call for P/N	\$1,704	\$77.89	4 Weeks	\$1,022
H-4050 (HSM460)	401-34435-00	999-000-9974	\$1,704	\$77.89	Stock	\$1,022
H-4050-P-H00AA-AB	193470	Call for P/N	\$1,704	\$77.89	4-6 Weeks	\$1,022
H-4050-P-H00AA	6144-01-802	999-000-9974	\$1,704	\$77.89	Stock	\$1,022
H-4050-P-H00AA-AA		999-001-0117	\$1,834	\$77.89	Stock	\$1,017
H-4050-P-H00AN	193471	999-001-0131	\$1,688	\$77.89	4 Weeks	\$1,013
H-4050-P-H00AX	6144-01-026	Call for P/N	\$1,747	\$77.89	4 Weeks	\$1,048

Contact Elwood:

Linda Richmond phone: 262-637-6591 x413 email: linda.richmond@elwood.com
 Lisa Woodward phone: 262-637-6591 x474 email: lisa.woodward@elwood.com
 John Hoepfner phone: 262-637-6591 x495 email: john.hoepfner@elwood.com



Elwood Corporation
 High Performance Motors
 2701 N. Green Bay Rd.
 Racine, WI 53404

http://www.elwood.com/gettys_rockwell.shtml

02/03/2012

PRICE LIST: H-SERIES REPLACEMENT MOTORS						
4-INCH FRAME						
Model Number	Rockwell P/N	Elwood P/N	List Price	Rare Earth Surchage	New Motor Availability*	Rebuild Price
H-4050-P-H01AA		999-001-0055	\$2,423	\$77.89	4 Weeks	\$1,454
H-4050-P-H01AA-AA		999-001-0157	\$2,553	\$77.89	4-6 Weeks	\$1,532
H-4050-P-H01AN	6144-02-856	Call for P/N	\$2,380	\$77.89	4-6 Weeks	\$1,428
H-4050-P-H04AA	193472	999-000-9998	\$2,358	\$77.89	Stock	\$1,415
H-4050-P-H04AA-AA		999-001-0114	\$2,488	\$77.89	4-6 Weeks	\$1,493
H-4050-P-H04AN	193473	Call for P/N	\$2,364	\$77.89	4-6 Weeks	\$1,418
H-4050-P-K00AA	195885	Call for P/N	\$1,715	\$77.89	4-6 Weeks	\$1,029
H-4050/24V-AB	401-34435-20	Call for P/N	\$2,374	\$77.89	4-6 Weeks	\$1,424
H-4050/24V	163626	Call for P/N	\$2,358	\$77.89	4-6 Weeks	\$1,415
H-4050/90V	401-34435-90	Call for P/N	\$2,358	\$77.89	4-6 Weeks	\$1,415
H-4075	163573	Call for P/N	\$1,828	\$116.84	4-6 Weeks	\$1,097
H-4075 (HSM490)	401-34436-00	999-000-9985	\$1,812	\$116.84	Stock	\$1,087
H-4075-R-H00AA	193474	999-000-9985	\$1,812	\$116.84	Stock	\$1,087
H-4075-H-H00AA-AA		999-001-0158	\$1,942	\$116.84	4 Weeks	\$1,165
H-4075-R-H00AN	193475	999-000-9989	\$2,045	\$116.84	Stock	\$1,227
H-4075-R-H01AA		Call for P/N	\$2,618	\$116.84	4-6 Weeks	\$1,571
H-4075-R-H04AA	193476	999-000-9996	\$2,553	\$116.84	Stock	\$1,532
H-4075-R-H04AN	193477	Call for P/N	\$2,591	\$116.84	4-6 Weeks	\$1,555
H-4075-R-J00AB		Call for P/N	\$2,645	\$116.84	4-6 Weeks	\$1,587
H-4075/24V-AB	163627	Call for P/N	\$2,553	\$116.84	4-6 Weeks	\$1,532
H-4075/24V (HSM490-B24)	401-34436-20	999-000-9996	\$2,553	\$116.84	Stock	\$1,532
W-4030-M-H00AA	6342-02-002	999-000-9994	\$2,778	\$50.06	4 Weeks	\$1,667
W-4030-M-H00AB	6342-02-004	Call for P/N	\$3,134	\$50.06	6 Weeks	\$1,880
W-4030-P-H00AA	6342-02-802	999-001-0015	\$2,778	\$50.06	4 Weeks	\$1,667
W-4030-P-H00AB	6342-02-008	Call for P/N	\$3,134	\$50.06	6 Weeks	\$1,880
W-4050-P-H00AA	6344-02-802	999-000-9993	\$3,063	\$77.89	4 Weeks	\$1,838
W-4050-P-H00AB	6344-02-004	999-001-0034	\$3,418	\$77.89	4 Weeks	\$2,051
W-4075-R-H00AA	6346-02-802	999-001-0044	\$3,181	\$116.84	4 Weeks	\$1,909
W-4075-R-H00AB	6346-02-002	Call for P/N	\$3,536	\$116.84	6 Weeks	\$2,122

*Availability is updated weekly and subject to change. Call to confirm.

**Consult factory for model numbers not listed.

***All motors built with original design, documentation, and equipment

Contact Elwood:

Linda Richmond phone: 262-637-6591 x413 email: linda.richmond@elwood.com

Lisa Woodward phone: 262-637-6591 x474 email: lisa.woodward@elwood.com

John Hoepfner phone: 262-637-6591 x495 email: john.hoepfner@elwood.com

http://www.elwood.com/gettys_rockwell.shtml

PRICE LIST: H-SERIES REPLACEMENT MOTORS						
6-INCH FRAME						
Model Number	Rockwell P/N	Elwood P/N	List Price	Rare Earth Surcharge	New Motor Availability*	Rebuild Price
1326AS-B630F-21		999-001-0139	\$3,132	\$86.31	4-6 Weeks	\$1,879
1326AS-B630F-21-K6		Call for P/N	\$3,781	\$86.31	4-6 Weeks	\$2,269
1326AS-B660E-21	163575	999-001-0046	\$3,773	\$171.57	4 Weeks	\$2,264
1326AS-B660E-21-A	195736	999-001-0030	\$4,422	\$171.57	4 Weeks	\$2,653
1326AS-B660E-21-K6	163629	999-000-9988	\$4,422	\$171.57	4 Weeks	\$2,653
1326AS-B660F-21-K6		999-001-0091	\$4,639	\$171.57	4 Weeks	\$2,783
1326AS-B690E-21		999-001-0045	\$3,990	\$257.89	Stock	\$2,394
1326AS-B690E-21-K6	163630	999-000-9999	\$4,639	\$257.89	4 Weeks	\$2,783
H-6100	163574	Call for P/N	\$2,601	\$86.31	4-6 Weeks	\$1,561
H-6100 (HSM610)	401-34437-00	Call for P/N	\$2,601	\$86.31	4-6 Weeks	\$1,561
H-6100-Q-H00AA	193478	999-001-0053	\$2,601	\$86.31	4 Weeks	\$1,561
H-6100-Q-H00AA-AA		999-001-0159	\$2,658	\$86.31	4-6 Weeks	\$1,595
H-6100-Q-H01AA		999-001-0128	\$3,585	\$86.31	4-6 Weeks	\$2,151
H-6100-Q-H04AA	193479	999-001-0039	\$3,477	\$86.31	4 Weeks	\$2,086
H-6100-Q-M200AA	195836	Call for P/N	\$3,396	\$86.31	4-6 Weeks	\$2,038
H-6100/24V BRK	163628	Call for P/N	\$3,477	\$86.31	4-6 Weeks	\$2,086
H-6100/24VBRK (HSM610B24)	401-34437-20	Call for P/N	\$3,477	\$86.31	4-6 Weeks	\$2,086
H-6200	163575	Call for P/N	\$3,773	\$171.57	4-6 Weeks	\$2,264
H-6200 (HSM620)	401-34438-00	999-000-9992	\$3,121	\$171.57	Stock	\$1,873
H-6200-Q-H00AA	193480	999-000-9992	\$3,121	\$171.57	Stock	\$1,873
H-6200-Q-H-X114	195847	Call for P/N	\$3,121	\$171.57	4-6 Weeks	\$1,873
H-6200-Q-H00AA-AA		999-001-0161	\$3,169	\$171.57	4-6 Weeks	\$1,901
H-6200-Q-H01AA		999-001-0127	\$4,088	\$171.57	4 Weeks	\$2,453
H-6200-Q-H04AA	193481	999-001-0056	\$3,979	\$171.57	4 Weeks	\$2,387
H-6200-Q-H04AA-AA		999-001-0161	\$4,009	\$171.57	4-6 Weeks	\$2,405
H-6200-Q-M200AA	195837	Call for P/N	\$3,745	\$171.57	4-6 Weeks	\$2,247
H-6200-Q-S00AX	6166-01-013	Call for P/N	\$4,505	\$171.57	4-6 Weeks	\$2,703
H-6200-Q-S04AX	6166-01-008	Call for P/N	\$5,431	\$171.57	4-6 Weeks	\$3,259
H-6200/24V BRK	164993	Call for P/N	\$3,979	\$171.57	4-6 Weeks	\$2,387
H-6200/24V BRK	163629	Call for P/N	\$3,979	\$171.57	4-6 Weeks	\$2,387
H-6200/24V BRK (HSM620B24)	401-34438-20	Call for P/N	\$3,979	\$171.57	4-6 Weeks	\$2,387
H-6300	163576	Call for P/N	\$3,916	\$257.89	4-6 Weeks	\$2,350
H-6300 (HSM630)	401-34439-00	999-001-0000	\$3,916	\$257.89	1-2 Weeks	\$2,350
H-6300-Q-H00AA	193482	999-001-0000	\$3,916	\$257.89	1-2 Weeks	\$2,350
H-6300-Q-H-X114 (SEE NOTE)	195848	Current Rev is identical to H-6300-Q-H00AA, Use EPN 999-001-0000				
H-6300-Q-H04AA	193483	999-001-0057	\$4,648	\$257.89	4 Weeks	\$2,789
H-6300-Q-H04AA-AA		999-001-0162	\$4,771	\$257.89	4-6 Weeks	\$2,863
H-6300-Q-K00AA	195884	Call for P/N	\$3,916	\$257.89	4-6 Weeks	\$2,350
H-6300-Q-K04AA		999-001-0097	\$4,756	\$257.89	4 Weeks	\$2,638
H-6300-Q-M200AA	195838	Call for P/N	\$4,237	\$257.89	4-6 Weeks	\$2,542
H-6300-Q-S00AD	6169-01-012	Call for P/N	\$4,711	\$257.89	4-6 Weeks	\$2,827
H-6300-Q-S200AA	195828	Call for P/N	\$3,532	\$257.89	4-6 Weeks	\$2,119
H-6300-S-J00AB	6169-01-007	Call for P/N	\$5,426	\$257.89	4-6 Weeks	\$3,256
H-6300-S-J00AB	6169-01-008	Call for P/N	\$5,728	\$257.89	4-6 Weeks	\$3,437
H-6300/24V BRK	163630	Call for P/N	\$4,648	\$257.89	4-6 Weeks	\$2,789
H-6300/24VBRK (HSM630B24)	401-34439-20	Call for P/N	\$4,648	\$257.89	4-6 Weeks	\$2,789
H-6300/90V (HSM630B90)	401-34439-90	Call for P/N	\$4,648	\$257.89	4-6 Weeks	\$2,789

*Availability is updated weekly and subject to change. Call to confirm.

**Consult factory for model numbers not listed.

***All motors built with original design, documentation, and equipment

Contact Elwood:

Linda Richmond phone: 262-637-6591 x413 email: linda.richmond@elwood.com

Lisa Woodward phone: 262-637-6591 x474 email: lisa.woodward@elwood.com

John Hoepfner phone: 262-637-6591 x495 email: john.hoepfner@elwood.com