

**2021 PRICE LIST: H-SERIES REPLACEMENT MOTORS**

**3-INCH FRAME**

Model Number	Rockwell P/N	Elwood P/N	List Price	New Motor Availability*	Rebuild Price
1326AS-B310H-21	163569	999-001-0011	\$2,125	Stock	\$1,275
1326AS-B310H-21-K3		999-001-0111	\$3,098	4-6 Weeks	\$1,859
1326AS-B330H-21	163570	999-001-0012	\$2,216	Stock	\$1,330
1326AS-B330H-21-A	195733	999-001-0027	\$3,556	4-6 Weeks	\$2,134
1326AS-B330H-21-K3		999-001-0065	\$3,179	4-6 Weeks	\$1,907
H-3007 (163569)	6131-01-802	999-001-0048	\$2,090	Stock	\$1,254
H-3007 (HSM307)	401-34432-00	999-001-0048	\$2,090	Stock	\$1,254
H-3007-N-H00AA	193458	999-001-0048	\$2,090	Stock	\$1,254
H-3007-N-H00AA-AA		999-001-0077	\$2,161	4-6 Weeks	\$1,297
H-3007-N-H01AA		999-001-0049	\$2,844	4-6 Weeks	\$1,706
H-3007-N-H01AA-AA		999-001-0155	\$2,916	4-6 Weeks	\$1,007
H-3007-N-H04AA	193459	999-001-0003	\$2,844	4-6 Weeks	\$1,706
H-3007-H-K00AA		999-001-0138	\$2,135	4-6 Weeks	\$778
H-3007/24V BRK	163623	999-001-0003	\$2,844	4-6 Weeks	\$1,706
H-3016		999-000-9982	\$2,116	Stock	\$1,270
H-3016 (HSM320)	401-34433-00	999-000-9982	\$2,116	Stock	\$1,270
H-3016-N-H00AA	193460	999-000-9982	\$2,116	Stock	\$1,270
H-3016-N-H00AA-AA		999-001-0154	\$2,188	4-6 Weeks	\$1,313
H-3016-N-H00AX	6133-01-008	999-001-0099	\$2,300	4-6 Weeks	\$1,380
H-3016-N-H01AA	195850	999-001-0054	\$2,924	4-6 Weeks	\$1,754
H-3016-N-H01AA-AA		999-001-0156	\$2,980	4-6 Weeks	\$1,078
H-3016-N-H04AA	193461	999-000-9997	\$2,924	1-2 Weeks	\$1,754
H-3016-N-K00AA	195814	999-001-0916	\$2,221	4-6 Weeks	\$1,333
H-3016-N-K04AA	6133-01-510	999-000-9986	\$3,021	4-6 Weeks	\$1,813
H-3016/24V BRK	163624	999-000-9997	\$2,924	1-2 Weeks	\$1,754
H-3016/24V BRK (HSM320B24)	401-34433-20	999-000-9997	\$2,924	1-2 Weeks	\$1,754
H-3016/90V BRK (HSM320B90)	401-34433-90	999-001-0054	\$2,924	4-6 Weeks	\$1,754
H-3016/Flying Leads	191893	Call for P/N	\$2,430	4-6 Weeks	\$1,458

\*Availability is updated weekly and subject to change. Call to confirm.

\*\*Consult factory for model numbers not listed.

\*\*\*All motors built with original design, documentation, and equipment

**2021 PRICE LIST: H-SERIES REPLACEMENT MOTORS**

**4-INCH FRAME**

Model Number	Rockwell P/N	Elwood P/N	List Price	New Motor Availability*	Rebuild Price
1326AS-B420G-21	195734	999-001-0005	\$3,540	Stock	2124
1326AS-B420G-21-AA		999-001-0060	\$4,440	4-6 Weeks	2664
1326AS-B420G-21-A		999-001-0028	\$4,722	4-6 Weeks	2833.2
1326AS-B420G-21-K4		999-001-0084	\$4,205	4-6 Weeks	2523
1326AS-B440G-21	163572	999-000-9990	\$3,671	Stock	2202.6
1326AS-B440G-21-A	195735	999-001-0029	\$4,926	4-6 Weeks	2955.6
1326AS-B440G-21-K4		999-001-0148	\$4,286	4-6 Weeks	2571.6
1326AS-B460F-21		999-001-0007	\$3,802	Stock	2281.2
1326AS-B460F-21-K4	163627	999-000-9987	\$4,366	Stock	2619.6
H-4030	163571	Call for P/N	\$2,228	4-6 Weeks	1336.8
H-4030 (HSM430)	401-34434-00	999-000-9980	\$2,228	Stock	1336.8
H-4030-M-H00AA	193462	999-001-0070	\$2,228	4-6 Weeks	1336.8
H-4030-M-H00AN	193463	Call for P/N	\$2,228	4-6 Weeks	1336.8
H-4030-M-H00AX	6142-01-002	999-001-0107	\$2,230	Stock	1338
H-4030-M-H04AA	193464	999-001-0096	\$3,080	4-6 Weeks	1848
H-4030-M-H04AX		999-001-0125	\$3,233	4-6 Weeks	1939.8
H-4030-P-H00AA	193465	999-000-9980	\$2,228	Stock	1336.8
H-4030-P-H00AA-AA		999-001-0130	\$2,299	4-6 Weeks	1379.4
H-4030-P-H00AN	193466	999-001-0469	\$2,228	4-6 Weeks	1336.8
H-4030-P-H00AX		999-001-0010	\$2,228	4-6 Weeks	1336.8
H-4030-P-H00KD	193467	999-001-0023	\$2,353	4-6 Weeks	1411.8
H-4030-P-H01AA		Call for P/N	\$3,080	4-6 Weeks	1848
H-4030-P-H04AA	193468	999-001-0098	\$3,080	4-6 Weeks	1848
H-4030-P-H04AN	6142-02-857	999-001-0428	\$3,095	4-6 Weeks	1857
H4030-P-H04AX		999-001-0147	\$3,233	4-6 Weeks	1939.8
H-4030/24V	401-34434-20	999-001-0098	\$3,080	4-6 Weeks	1848
H-4030/24V (HSM430B24)		Call for P/N	\$3,080	4-6 Weeks	1848
H-4030/24V-AB	163625	Call for P/N	\$3,080	4-6 Weeks	1848
H-4050	163572	Call for P/N	\$2,555	4-6 Weeks	1533
H-4050 (HSM460)	401-34435-00	999-000-9974	\$2,555	4-6 Weeks	1533
H-4050-P-H00AA-AB	193470	Call for P/N	\$2,555	4-6 Weeks	1533
H-4050-P-H00AA	6144-01-802	999-000-9974	\$2,555	4-6 Weeks	1533
H-4050-P-H00AA-AA		999-001-0117	\$2,660	4-6 Weeks	1596
H-4050-P-H00AN	193471	999-001-0131	\$2,555	4-6 Weeks	1533
H-4050-P-H00AX	6144-01-026	999-001-0305	\$2,618	4-6 Weeks	1570.8
H-4050-P-H01AA		999-001-0055	\$3,632	4-6 Weeks	2179.2
H-4050-P-H01AA-AA		999-001-0157	\$3,736	4-6 Weeks	2241.6
H-4050-P-H01AN	6144-02-856	999-001-0322	\$3,632	4-6 Weeks	2179.2
H-4050-P-H04AA	193472	999-000-9998	\$3,532	4-6 Weeks	2119.2
H-4050-P-H04AA-AA		999-001-0114	\$3,637	4-6 Weeks	2182.2
H-4050-P-H04AN	193473	999-001-0347	\$3,532	4-6 Weeks	2119.2
H-4050-P-K00AA	195885	Call for P/N	\$3,532	4-6 Weeks	2119.2
H-4050/24V-AB	401-34435-20	Call for P/N	\$3,580	4-6 Weeks	2148
H-4050/24V (HSM460B24)	163626	999-000-9998	\$3,532	4-6 Weeks	2119.2
H-4050/90V	401-34435-90	Call for P/N	\$3,532	4-6 Weeks	2119.2
H-4075	163573	Call for P/N	\$2,694	4-6 Weeks	1616.4
H-4075 (HSM490)	401-34436-00	999-000-9985	\$2,694	Stock	1616.4
H-4075-R-H00AA	193474	999-000-9985	\$2,694	Stock	1616.4
H-4075-R-H00AA-AA		999-001-0158	\$2,799	4-6 Weeks	1679.4
H-4075-R-H00AN	193475	999-000-9989	\$2,694	4-6 Weeks	1616.4
H-4075-R-H01AA		Call for P/N	\$3,920	4-6 Weeks	2352
H-4075-R-H04AA	193476	999-000-9996	\$3,920	4-6 Weeks	2352
H-4075-R-H04AN	193477	999-001-0346	\$3,920	4-6 Weeks	2352
H-4075/24V-AB	163627	Call for P/N	\$3,920	4-6 Weeks	2352
H-4075/24V (HSM490-B24)	401-34436-20	999-000-9996	\$3,920	4-6 Weeks	2352
OBSOLETE P/N'S					
H-4030-P-J00AB	6142-01-032	999-001-0198	N/A	Obsolete	N/A
H-4030-P-J04AB	6142-01-028	Call for P/N	N/A	Obsolete	N/A
H-4075-R-J00AB		Obsolete	N/A	Obsolete	N/A

\*Availability is updated weekly and subject to change. Call to confirm.

\*\*Consult factory for model numbers not listed.



Elwood Corporation  
High Performance Motors  
2701 N. Green Bay Rd.  
Racine, WI 53404

<http://www.elwood.com/H-Series.html>

May 13, 2022

2021 PRICE LIST: H-SERIES REPLACEMENT MOTORS					
4-INCH FRAME					
Model Number	Rockwell P/N	Elwood P/N	List Price	New Motor Availability*	Rebuild Price

\*\*\*All motors built with original design, documentation, and equipment

**2021 PRICE LIST: H-SERIES REPLACEMENT MOTORS**

**6-INCH FRAME**

Model Number	Rockwell P/N	Elwood P/N	List Price	New Motor Availability*	Rebuild Price
1326AS-B630F-21		999-001-0139	\$4,471	6 Weeks	\$2,683
1326AS-B630F-21-K6		Call for P/N	\$6,246	6 Weeks	\$3,748
1326AS-B660E-21	163575	999-001-0046	\$5,709	6 Weeks	\$3,425
1326AS-B660E-21-A	195736	999-001-0030	\$6,621	6 Weeks	\$3,973
1326AS-B660E-21-K6	163629	999-000-9988	\$7,496	6 Weeks	\$4,498
1326AS-B660F-21-K6		999-001-0091	\$7,496	6 Weeks	\$4,498
1326AS-B690E-21		999-001-0045	\$7,246	6 Weeks	\$4,348
1326AS-B690E-21-K6	163630	999-000-9999	\$8,321	6 Weeks	\$4,993
H-6100	163574	Call for P/N	\$3,870	6 Weeks	\$2,322
H-6100 (HSM610)	401-34437-00	Call for P/N	\$3,870	6 Weeks	\$2,322
H-6100-Q-H00AA	193478	999-001-0053	\$3,870	6 Weeks	\$2,322
H-6100-Q-H00AA-AA		999-001-0159	\$3,995	6 Weeks	\$2,397
H-6100-Q-H01AA		999-001-0128	\$6,246	6 Weeks	\$3,748
H-6100-Q-H04AA	193479	999-001-0039	\$6,246	6 Weeks	\$3,748
H-6100-Q-K00AA		999-001-0479	\$4,059	6 Weeks	\$1,758
H-6100/24V BRK	163628	Call for P/N	\$6,246	6 Weeks	\$3,748
H-6100/24VBRK (HSM610B24)	401-34437-20	Call for P/N	\$6,246	6 Weeks	\$3,748
H-6200	163575	Call for P/N	\$5,341	6 Weeks	\$3,205
H-6200 (HSM620)	401-34438-00	999-000-9992	\$5,341	6 Weeks	\$3,205
H-6200-Q-H00AA	193480	999-000-9992	\$5,341	6 Weeks	\$3,205
H-6200-Q-H-X114	195847	Call for P/N	\$5,341	6 Weeks	\$3,205
H-6200-Q-H00AA-AA		999-001-0160	\$5,645	6 Weeks	\$3,387
H-6200-Q-H01AA		999-001-0127	\$6,621	6 Weeks	\$3,973
H-6200-Q-H04AA	193481	999-001-0056	\$6,621	6 Weeks	\$3,973
H-6200-Q-H04AA-AA		999-001-0161	\$6,745	6 Weeks	\$4,047
H-6200/24V BRK	164993	Call for P/N	\$6,621	6 Weeks	\$3,973
H-6200/24V BRK	163629	Call for P/N	\$6,621	6 Weeks	\$3,973
H-6200/24V BRK (HSM620B24)	401-34438-20	Call for P/N	\$6,621	6 Weeks	\$3,973
H-6300	163576	Call for P/N	\$6,996	6 Weeks	\$4,198
H-6300 (HSM630)	401-34439-00	999-001-0000	\$6,996	Stock	\$4,198
H-6300-Q-H00AA	193482	999-001-0000	\$6,996	Stock	\$4,198
H-6300-Q-H04AA	193483	999-001-0057	\$8,121	6 Weeks	\$4,873
H-6300-Q-H04AA-AA		999-001-0162	\$8,370	6 Weeks	\$5,022
H-6300-Q-K00AA	195884	Call for P/N	\$7,120	6 Weeks	\$4,272
H-6300-Q-K04AA		999-001-0097	\$8,245	6 Weeks	\$4,947
H-6300/24V BRK	163630	Call for P/N	\$8,121	6 Weeks	\$4,873
H-6300/24VBRK (HSM630B24)	401-34439-20	Call for P/N	\$8,121	6 Weeks	\$4,873
H-6300/90V (HSM630B90)	401-34439-90	Call for P/N	\$8,121	6 Weeks	\$4,873
OBSELETE P/N'S					
H-6100-Q-M200AA	195836	N/A	N/A	Obsolete	N/A
H-6200-Q-M200AA	195837	N/A	N/A	Obsolete	N/A
H-6200-Q-S00AX	6166-01-013	N/A	N/A	Obsolete	N/A
H-6200-Q-S04AX	6166-01-008	N/A	N/A	Obsolete	N/A
H-6300-Q-H-X114 (SEE NOTE)	195848	Current Rev is identical to H-6300-Q-H00AA, Use EPN 999-001-0000			
H-6300-Q-M200AA	195838	N/A	N/A	Obsolete	N/A
H-6300-Q-S00AD	6169-01-012	N/A	N/A	Obsolete	N/A
H-6300-Q-S200AA	195828	N/A	N/A	Obsolete	N/A
H-6300-S-J00AB	6169-01-007	N/A	N/A	Obsolete	N/A
H-6300-S-J00AB	6169-01-008	N/A	N/A	Obsolete	N/A

\*Availability is updated weekly and subject to change. Call to confirm.

\*\*Consult factory for model numbers not listed.

\*\*\*All motors built with original design, documentation, and equipment